



Martin Operating Partnership L.P.

Technical Service Bulletin

Unimark® Global Automatic Transmission Fluid OEM Specification Claim Set

NO. TB 170310.2

SFS = Suitable for Service (Suitable for Use)

| | |
|--|----------|
| Acura ATF- Z1 | SFS |
| Aisin Warner JWS 3309 (T-IV), JWS 3324 (WS), AW - 1 | SFS |
| Allison C-3, C-4 | SFS |
| American Motors ATF+3 (MS7176E), ATF+4 (MS9602) | SFS |
| ATF RED 1, RED 1K | SFS |
| Audi G 055 025 A2 (JWS 3309) | SFS |
| Audi/VW G 052 990 | SFS |
| BMW LA2634, 7045E, ETL-8072B | SFS |
| BMW JWS 3309 (T-IV) | SFS |
| BMW MINI | SFS |
| Caterpillar Power Shift TO-2 | SFS |
| Chrysler ATF+, ATF+2, ATF+3, ATF+4 | SFS |
| Chrysler/Dodge MOPAR AS 68 RC (T-IV), JWS 3309 | SFS |
| Daewoo LT 71141 | SFS |
| Daihatsu AMMIX ATF D-II / D-III SP, Friend ATF D-III | SFS |
| FIAT T-IV type, JWS 3309 | SFS |
| Ford M2C138-CJ, M2C166-H | SFS |
| Ford Mercon® | SFS |
| Ford Mercon® V | Licensed |
| Ford FNR5, WSS M2C 138CJ, 166H | SFS |
| Ford WSS M2C 922A1, 924A (XT-8-QAW) JWS 3309 | SFS |
| Fuso ATF-II, ATF-SPIII, ATF-A4 | SFS |
| GM Dexron®, II, II-D, II-E, III-G, III-H, TASA | SFS |
| GM 9986195 (Aisin AW, JWS 3309) | SFS |
| Honda ATF-Z1 (except in CVTs), ATF Ultra II, DW-1 | SFS |
| Hyundai SP-II, SP-III, SP-IV, SP-IVM, SP-IV-RR, Dex II | SFS |
| Hyundai JWS 3314, NWS 9683 | SFS |
| Isuzu BESCO ATF-II / ATF-III, ATF-SP, SCS Fluid | SFS |
| Jaguar ATF 3403-M115 | SFS |
| JASO M315-2013 1A, M315-2013 1A-LV, M315-2013 2A | SFS |
| Jeep (ATF+3, ATF+4) | SFS |
| JWS 3317 | SFS |

| | |
|--|-----|
| Kia SP-II, SP-III, SP-IV, SP-IVM, SP-IV-RR | SFS |
| Kia JWS 3314, NWS 9683 | SFS |
| Kia Dex II | SFS |
| Kia Red 1 | SFS |
| Lexus JWS 3309 | SFS |
| Mazda ATF D-II, M-III, M-V | SFS |
| Mazda ATF FZ, F-1, S-1, N-1 | SFS |
| Mazda ATF 3317 | SFS |
| Mini Cooper T-IV | SFS |
| Mitsubishi Diaqueen SK, SP-II, SP-III, AW, J2, J3, | SFS |
| Mitsubishi Diaqueen ATF PA | SFS |
| Mitsubishi Fuso ATFA-4 | SFS |
| NAG 1 (Chrysler, Jeep, Cherokee) | SFS |
| Nissan Matic Fluid C, D, J, K, N4, S | SFS |
| Opel (all vehicles) | SFS |
| Porsche T-IV (JWS 3309) | SFS |
| Renault Samsung SATF-D | SFS |
| SAAB T-IV (JWS 3309) | SFS |
| SAAB 93 165 147 | SFS |
| Saturn T-IV (JWS 3309) | SFS |
| Scion (all vehicles) | SFS |
| Subaru ATF, ATF 5AT, ATF HP | SFS |
| Subaru Dexron II, ATF for Vivio 3 speed | SFS |
| Suzuki AT OIL 5D06, ATF 2326, ATF 2384K | SFS |
| Suzuki JWS 3309, ATF 3314, ATF 3317 | SFS |
| Texaco 7045-E, 8072B, N402 | SFS |
| Toyota ATF D-II, D-III, T-III, T-IV, WS | SFS |
| Vickers M-2950-S, I-286-S | SFS |
| Volvo CE 97340 | SFS |
| VW G-055-025 A2 (JWS 3309) | SFS |
| ZF TE-ML 09 | SFS |
| ZF TE-ML 11A, 11B | SFS |