



Martin Operating Partnership L.P.

# Technical Service Bulletin

## SynGard® Low Viscosity Multi-Vehicle Automatic Transmission Fluid OEM Specification Claim Set

NO. TB 170310.1

SFS = Suitable for Service (Suitable for Use)

Acura ATF- Z1	SFS
Aisin Warner JWS 3309 (T-IV), JWS 3324 (WS), AW - 1	SFS
Allison C-3, C-4	SFS
American Motors ATF+3, ATF+4	SFS
ATF RED 1, RED 1K	SFS
Audi 5 HP LT71141 (ZF 5 HP 18FL/19FL/24A)	SFS
Audi G 052 162 A1/A2, G 052 162 (ZF Lifeguardfluid 5)	SFS
Audi G 055 025 A2 (JWS 3309)	SFS
Audi/VW G 052 990	SFS
BMW LA2634, 7045E, ETL-8072B	SFS
BMW JWS 3309 (T-IV), MINI	SFS
BMW LT71141 (ZF 5 HP 18FL/19FL/24A)	SFS
BMW ZF 5HP 18FL, 5HP24, 5HP30	SFS
Caterpillar Power Shift TO-2	SFS
Chrysler ATF+, ATF+2, ATF+3 (MS7176E), ATF+4 (MS9602)	SFS
Chrysler/Dodge MOPAR AS 68 RC (T-IV), JWS 3309	SFS
Chrysler/Dodge/Jeep 68043742AA	SFS
Daewoo / Esso LT 71141	SFS
Daihatsu AMMIX ATF D-II / D-III SP	SFS
FIAT T-IV type, JWS 3309	SFS
Ford M2C138-CJ, M2C166-H	SFS
Ford Mercon®	SFS
Ford Mercon® LV	Licensed
Ford FNR5, WSS M2C: 138CJ / 166H	SFS
Ford WSS M2C 922A1, 924A (XT-8-QAW) JWS 3309	SFS
Fuso ATF-II, ATF-SPIII, ATF-A4	SFS
GM Dexron®, II, II-D, II-E, III-G, III-H, TASA, GM9986195	SFS
GM Dexron® VI	Licensed
Honda ATF-Z1 (except in CVTs), DW-1	SFS
Hyundai SP-II, SP-III, SP-IV, SP-IVM, SP-IV-RR, Dex II	SFS
Hyundai JWS 3314, NWS 9683	SFS
Nissan Matic-D, Matic-J, Matic-K, Matic-S	SFS
Isuzu BESCO ATF-II / ATF-III, ATF-SP, SCS Fluid	SFS
Jaguar ATF 3403-M115, 3403, JLM20238	SFS
Jaguar LT71141, ZF 5HP24	SFS
JASO M315-2013 1A, M315-2013 1A-LV, M315-2013 2A	SFS
Jeep (ATF+3, ATF+4)	SFS

Kia ATF SP-II, SP-III, SP-IV, SP-IVM, SP-IV-RR	SFS
Kia JWS 3314, NWS 9683	SFS
Kia Dex II	SFS
Kia Red 1	SFS
Lexus JWS 3309	SFS
Mazda ATF D-II, M-III, M-V	SFS
Mazda ATF FZ, F-1, S-1, N-1	SFS
Mazda ATF 3317	SFS
Mini Cooper T-IV	SFS
Mitsubishi Diaqueen SK, SP-II, SP-III, AW, J2, J3	SFS
Mitsubishi Diaqueen ATF PA	SFS
NAG 1 (Chrysler, Jeep, Cherokee)	SFS
Nissan Matic Fluid C, D, J, K, S	SFS
Opel (all vehicles)	SFS
Peugeot ZF 4HP20	SFS
Porsche ZF 5HP19FL, ZF 5HP20, LT71141	SFS
Porsche ATF 3403-M115, T-IV (JWS 3309)	SFS
Renault Samsung SATF-D	SFS
SAAB T-IV (JWS 3309), 93 165 147	SFS
Saturn T-IV (JWS 3309)	SFS
Scion (all vehicles)	SFS
Shell 3403, M115, LA 2634	SFS
Subaru ATF, ATF 5AT, ATF HP	SFS
Subaru Dexron® II	SFS
Suzuki AT OIL 5D06, ATF 2326, ATF 2384K	SFS
Suzuki JWS 3309, ATF 3314, ATF 3317	SFS
Texaco 7045-E, 8072B, N402	SFS
Toyota ATF D-II, D-III, T-III, T-IV, WS	SFS
Vickers M-2950-S, I-286-S	SFS
Voith H55.6335.xx (G607)	SFS
Volvo CE 97340	SFS
VW 5 HP: (ZF 5 HP 30), (18FL, 30), (19FL, 24A)	SFS
VW G-055-025 A2 (JWS 3309)	SFS
VW G-052-162 (ZF Lifeguardfluid 5), TL 521 62	SFS
ZF all 3 & 4 speed transmission	SFS
ZF TE-ML 09, TE-ML 11A, 11B	SFS
ZF TE-ML 11A, 11B	SFS